



# **APPENDIX C**

## **Photoplates**



## APPENDIX C

### MURPHY OIL COMPANY LTD. TUPPER PIPELINE THIRD YEAR POST CONSTRUCTION MONITORING

*Photograph 1: Looking southwest along the ROW from chainage 0+050 showing increased vegetation growth since the 2010 PCMP assessment.*



*Photograph 2: Scentless chamomile identified between chainages 1+250 and 1+330*







## APPENDIX C

### MURPHY OIL COMPANY LTD. TUPPER PIPELINE THIRD YEAR POST CONSTRUCTION MONITORING

*Photograph 3: Looking west along the ROW from chainage 1+300 showing roach above the pipeline trench.*



*Photograph 4: Erosion along quad trail (facing south, chainage 2+725).*

