December 9, 2011

THIRD YEAR POST CONSTRUCTION MONITORING PROGRAM REPORT BASED ON THE APPLICABLE REQUIREMENTS WITHIN THE FILING MANUAL UNDER SECTION 58 OF THE NATIONAL ENERGY BOARD ACT:

MURPHY TUPPER PIPELINE RIGHT-OF-WAY FROM PLANT SITE a-21-B, 93-P-9 TO BRAINARD METER STATION WITHIN NE 1/4, SECTION 7, TOWNSHIP 74, RANGE 12, W6M

Submitted to:
Murphy Oil Company Ltd.
10218- 10 Street
Dawson Creek, BC
V1G 3T4
Attention: Ryan Dick

REPORT

Report Number: 11-1492-0191

Distribution:

2 Copies - Murphy Oil Company Ltd.

1 Copy - Golder Associates Ltd.

A world of capabilities delivered locally

Golder Associates

Table of Contents

1.0 INTRODUCTION **1**

2.0 SCOPE OF WORK AND METHODOLOGY **1**

3.0 PROJECT DESCRIPTION **2**

4.0 ASSESSMENT RESULTS **2**

4.1 Soil Assessment 2

4.1.1 Admixing 4

4.1.2 Stoniness 4

4.1.3 Contour Restoration 5

4.1.4 Erosion Potential 5

4.2 Vegetation Assessment 5

4.2.1 Vegetative Cover 6

4.2.2 Weed Issues 6

4.2.3 Woody Debris 6

4.3 Watercourse Assessment 7

4.3.1 Unnamed tributary to Tupper Creek 8

4.3.2 Tupper Creek 8

4.3.3 Unnamed tributary to Albright Creek 8

5.0 LAND OWNER COMMENTS **8**

6.0 CONCLUSIONS AND RECOMMENDATIONS **10**

7.0 CLOSURE **11**

8.0 REFERENCES **12**

TABLES

Table 1: Soil Characteristics of Outstanding Issues Identified During Third Year PCMP (2011) 2

Table 2: Outstanding Vegetation Issues Identified During Third Year PCMP (2011) 5

Table 3: Outstanding Watercourse Issues Identified During the Third Year PCMP (2011) 7

Table 4: Landowner Comments Identified During the Third Year PCMP (2011) 9

APPENDICES

Appendix A
Survey Diagrams

Appendix B
Figures

Appendix C
Photoplates

APPENDIX D
Seeding Recommendations