

## IN THE MATTER OF THE NATIONAL ENERGY BOARD ACT, FOLLOWING AN ORDER UNDER SECTION 51.1

On	May 21 2015 at approx. 10:30 a.m.		, the undersigned National Energy Board Inspection Officer hereby		
	Da	ate/time			
notifies	of Westcoast I		Energy Inc.	ergy Inc. that the hazardous or detrimental situation	
	Со	mpany Representative and compa	ny name		
describe	in Order No. <b>SCB-001-2015</b>		has been remedied to the satisfaction of the Inspection Officer.		
		Inspection Officer order			
Therefore	e, Suspend	led work may resume, and/o	or		
	✓ the meas	sures specified in the order	have been satisfied	l.	

		1137	
	Name	IO Designation #	Telephone
Inspection Officer	25 May 2015		
	Date	 Signature	
	Centre 10 – 517, 10th Avenue SW Calgary AB T2R 0A8		

Revised July 2014 Document #: 282393 Activity or Incident #: \_\_\_\_\_

